UNCLASSIFIED

AD NUMBER AD010761 CLASSIFICATION CHANGES TO: unclassified FROM: confidential

TO:

Approved for public release, distribution unlimited

LIMITATION CHANGES

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 07 NOV 1952. Other requests shall be referred to Office of Naval Research, Arlington, VA 22203.

AUTHORITY

30 Nov 1964, DoDD 5200.10; ONR ltr dtd 9 Nov 1977 Reproduced by

Armed Services Technical Information Agency DOCUMENT SERVICE CENTER

KNOTT BUILDING, DAYTON, 2, OHIO

AD —

CONFIDENTIAL

7995119



87825



MODEL: 309A & 319

REPORT NO. 3

APPLICATION OF CIRCULATION CONTROL TO AN AIRPIANE OF MILITARY LIAISON TYPE

NONR CONTRACTS 234(00) AND 856(00)

Cessna Aircraft Company Wichita, Kansas

Aircraft Company Wichita, Kansas

PERIODIC PROGRESS REPORT

MODEL309A & 319: REPORT NO. 3 APPLICATION OF CIRCULATION CONTROL TO AN AIRPLANE OF MILITARY LIAISON TYPE. NONE CONTRACTS 234(00) AND 856(00)

REPORT DATE:

7 November 1952

PREPARED BY: E. G. Blosser

WITNESSED BY:

J. W. Fisher

APPROVED BY:

A. N. Petroff

PHEPARED BY EGB & JWF DATE 11-7-52

CHECKED BY ANP DATE 11-7-52

CESSNA AIRCRAFT CO.

PAGE. 1

MODEL 309A & 319

FMRM 484

NONE CONTRACTS 234(00) and 856(00)

APPLICATION OF CIRCULATION CONTROL TO AN AIRPLANE OF MILITARY LIAISON TYPE

This report covers the period from 5 September 1952 to 1 November 1952.

CESSNA MODEL 309 - CONTRACT NO. 234(00)

Analysis

Comparative study to evaluate efficiency of the pumping system installed on Cessna Model 309A was initiated and conducted in three phases:

- 1. Tests of the mock-up (presented in University of Wichita Report No. 071).
- 2. Tests of the system on the ground.
- 3. Flight tests of system performance.

Phase two has been completed, and results show the BLC system requires 21.7 shaft horsepower to deliver a total flow quantity of 102 ft³/sec. These values were determined by total and dynamic pressure surveys in conjunction with measured electrical current and voltages, and with known generator efficiency. Measurements were made with engine operating at 1500 rpm, the flap deflected full down (450), and with the aileron neutral and fully dropped (300 down). Aileron position had an insignificant effect on power and quantity flow.

An overall efficiency of 20.5 percent including duct losses were determined from the product of individual component efficiencies. These were computed from horsepower input and output measured electrically, at the generator and the fan motors, and in the following manner for the duct:

Duct input $= P \times Q/550$ where P is the pressure rise across the fans , and Q is the flow quantity.

Duct output = Q x qd/550 where qd is average dynamic pressure in the blow-ing slot.

The individual component efficiencies are shown in Figure 1.

PERIODIC PROGRESS REPORT
PREPARED BYEAB & JWF DATE 11-7-52
CHECKED BY AIP DATE 11-7-52

CESSNA AIRCRAFT CO.
WICHITA, KANSAS

M 484

Figure 2 illustrates how the engine shaft horsepower required by the BLC system is divided among each component. The greatest power losses are electrical and occur in the generator and fan motors; however, the efficiencies of generator, motor fan combination, and ducting are approximately the same. This indicates that an equal improvement in efficiency for any of the three components would result in the same system improvement if other component efficiencies were constant. Actually, the motor fan units were operating very close to peak condition, and an improved duct efficiency would be accompanied by a slight decrease in motor-fan efficiency, but this overall effect would be quite small.

The range of duct losses measured during the ground test is illustrated by Figure 3. Friction effect and length of the forward ducts account for greater losses. The wide range of experimental values for similar ducts, but opposite wing panels, signifies the difficulty of accurately predicting losses in projected designs.

The analysis of results collected for phases 2 and 3 will be reported by Cessna Report 1309-7.

Design and Construction

Upon completion of the ground tests on the electric motor fan circulation control system in the 309A, the beginning of the flight tests were held up pending the delivery of the DR-2 Variation Camera.

Longitudinal static stability flight tests were made without this camera, since the required information could be obtained by use of a Gray Audograph. These tests were completed on 24 October 1952. The results of these and further flight tests will be covered by Cessna Report 1309-6.

PREPARED BEGS & JWF DATE 11-7-52
CHECKED BY. AND DATE 11-7-52

CESSNA AIRCRAFT CO.

PAGE - 3

MODEL _ 309A & 319

From the preceeding flight tests it was determined that aileron and rudder trim tabs were required for dynamic stability and control flight tests. Engineering and design of the lateral trim system is completed, and the directional trim system will be completed by 7 November 1952.

An extensive investigation of the ground tests results indicated that a somewhat different method of instrumentation of the blowing slot was needed to determine the quantity flow through the wing. For this reason twenty-four pitot static heads were located at the exit to the blowing slot and connected to a multiple tube manameter in the fuselage. The airplane is now in the process of being flight tested to determine quantity flow.

PERIODIC PROGRESS REPORT

PREPARED BYEGB & JWF DATE 11-7-52
ANP 11-7-52

CESSNA AIRCRAFT CO.

PAGI.

REPORT NO 3

MODEL 309A & 319

CECSNA NODEL 319 - CONTRACT NO. 856(00)

Analysis

A preliminary study of systems for the pumping of air used by BLC on air-craft was partially completed and presented in Cessna Report No. 1309-5 under the title, "Investigation of Boundary Layer Pumping Systems" by R. K. Wattson, Jr.

Design and Construction

The 0.6 scale model of the 319 wing is nearing completion at Wichita University. The model is scheduled to be placed in the tunnel for the start of the tests on 1 December 1952.

Tests on the full scale vortex suction duct mock-up of the wing were completed at Wichita University. These tests were conducted to determine final duct diameter and configuration of this duct.


Design work on the Model 319 has been started. To date the following drawings have been started.

12319-6 Structure Assembly - Wing

12319-7 Cabin Modification

12319-8 Tail Wheel Installation

12319-9 Bulkhead Contour (Station 214.375)



NEIDEN		PT. NO. 3			Page 6					
	P. C. Marcel			NODEL 309						
-alp at the adjustment of				ROUND TE			4			
		NEUTRAL	17	(45°)	_					
	NOINE	D 1500 F	PM							
		Paragram and an analysis of the state of the	•			,				
			20			, ,				
	,		EV ~	S Q	* 1					
				ENERAIT DRIVE						
ne promptediene.			15	5]		**************************************				
••	4- ,	٥		5	3	• • • • • • • • • • • • • • • • • • •				
 auginta 	,	A S		SHAFT	4-0108-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	**************************************				
		Ϊ		OUTPUT	5 ô 2 m) Q				
t ti reederstate = =				マース・ナノー	្រំ 🖁	2				
			5	GENERATOR GENERATOR MOTOR INPUT	<u>}</u> 89	•				
Perencia de La Mandelle de Luci. El				MO SE		**************************************				
		•		S S	20	· · · · · · · · · · · · · · · · · · ·				
,	• Pow	ER OUT	- 0 TUC	AT BLOW	NG BLOT	Anner of the State	;			
٠	(DYN)	AMIC PRE	SOUR	at Blow Ex Flow G	NUMNTITY/S	(0)				
	*					e dikananga nau gala (kagan ye ya yi a - uan a !				
				A	*	. 4				
 -	.]	1	1 4	; 	CONFIDENTIAL			

10-<u>9-</u>52 H.L. III

£	IC PRO	···	REPT.	NO. 3			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	,	·····		Pa	g e 7	
CON	FIDEN	LIAĻ		-	-				<u> </u>					
• · · · · · · · · · · · · · · · · · · ·						Gri	hodel round	Test	١ .			-		
	-	red ir direm kuri ğ rişke diremiye				Fia	uct i	1 Dow	m (45°)					
; }*			 	-	· · · · · · · · · · · · · · · · · · ·		ron_			·			-	
· · · · · · · · · · · · · · · · · · ·						Ene	ine e	1200	R.PM					
			<u> </u>		.1		-			;				
								;		,				
	1	•					• •		-					
			- 80						- 10.			. ,		-
	Du	of Los		* -				1	• .					
	Č	/F+)	20-				1		1	7			*	- 1
1						ا فدار	36		- •					
	1 164	a capang angangan va a	10		S		11E		-	,		-		
1	•	; - <i>a + a pa</i> aa		A CO			*	A - 1		ediguiselle de disciplishen.				
•	, ,			0	H	0 9	2	Ο		0				. !
1						namic Blowin	# S					• · · · · · · · · · · · · · · · · · · ·		
! !						Fig	+*) . 5	1						
***** *** *** *** *** *** *** *** ***		8	piones Etween	Are I	Pre	8547	RISE	Acre	Des Th					
				d The Blot		imio F	>re s 8	ire in	The	,				
1							- ,	-		я	1			
		tora anno arrows a ser si										} !	 	